

DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER		MODEL AND GRADE		ORDER	
12/21/90		12/21/90		12/21		6419793		700 22-250		R	

ACCESSORIES: SCOPE BRNS

FROM:	SHIP TO:
JIM MASTERS WESTERN STORES 400 GILMER ST SULPHUR SPRINGS TX 75482	JIM MASTERS WESTERN STORES 400 GILMER ST SULPHUR SPRINGS TX 75482

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	FROM DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☒ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Discharges prematurely when bolt closed after loading"

MAIN FAULT: Cannot duplicate complaint. However, trigger assembly is extremely dirty and has been improperly adjusted out of factory as evidenced by foreign material on adjustment screws. Trigger pull 6 pounds, insufficient over-travel, because over-engaged. Rifle has not been properly maintained.

Offer replacement trigger assembly at 1/2 normal cost, as gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
LEW					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE