

N/700 Const. Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: Good R #: 014609
OUTSIDE WORK: SCREWS MOUNTED DATE: 7-21-72
FROM: LEO D. JONES
FIRED AMMO TYPE: 150 GR. SUPER X WARREN, OHIO
& CONDITION: _____ GUN #: 6282457
PROOF: R.E.P.-B INSP.: 79 TEST: 87 CODE: ES-10/69
HEADING: O.K. SMK./CAL.: 7MM REM. MAG.
BREACH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: _____ APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .005 (MIN. IS .020)
STEP IN FACE OF BOLT. TRIGGER NOT DE-BURRED.

COMPLAINT: "UPON OPENING THE BOLT THE GUN DISCHARGED.
"SHELLS HARD TO CHAMBER"

INCIDENT: FOLLOW DOWN, CLOSES HARD

COMMENTS: FOLLOW DOWN WAS CAUSED BY .005 ENGAGEMENT
AND SLIGHT TRIGGER BIND. THE CLOSES HARD WAS DUE
TO THE STEP IN THE BOLT FACE WHICH CREATED A MIN.
HEADER CONDITION NOT PICKED UP BY THE HEADING
DUMMY.