

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-28177

AL CUSTOMER ORDER NO.

RECEIVED 15/92	DATE OPENED 12/22/92	DATE CODE AE 3-84	SERIAL NUMBER B6550258	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN BDL
ACCESSORIES W/STUDS			SCOPE BASE		

M:

KARRERS GUNATORIUM
5323 N ARGONNE RD
SPOKANE

WA 99212

SHIP TO:

KARRERS GUNATORIUM
5323 N ARGONNE RD
SPOKANE

WA
99212

CUST NO: 007107 WITH

QUANTITY NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
CONDITION					REPAIR CHARGE
NEW					EXCISE
SLIGHTLY WORN					TAX
VERY WORN					INSURANCE
UNREPAIRABLE					UPS
REPAIRED					PARCEL POST
					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
TRIGGER GROUP		B2			E1	F1
TRIGGER ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
TRIGGER ASSY.		B5		D2	E4	F4
TRIGGER			C1	D3	E5	F5
AL			C2			

FAULT

Unable to duplicate Customer's Concern. However, during inspection it was noted that the bolt stop is damaged, and the trigger assembly is contaminated with rust. For maintenance. Slightly 1984 Trigger Pull tests, Left 0.11

COMMENTS

Offer to replace trigger assembly & repair at 1/2 normal cost as gesture of good will.

REPAIRMAN	PROOF	CLEAN ☒	TEST ☒	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 02649