

June 19, 1981

Dear Sir,

Please replace this faulty
trigger on the Remington.
Several times it has now fired.

Thank You
Gary T. Halishak
Route 2 Box 422
Ladette, Mich.
49837

MODEL: 600

S/N: 77404

DATE: 6-29-81

FROM: GARY HALISHAK
RTE 2 BOX 422
GLADSTONE MI

QTY: 1 A6654959

CODE: DO = 9-78

CA./CAL.: 308

CHECKED BY: M. HARTZ

APPROVED: 4/9/81

APPROVED: PH 9/1/81

APPROVED: F.W. 9/1/81

APPROVED: 9/1/81

SS FIRED SEVERAL

no complaints.

assemble new fire control - clear area in
stock for fire control.