



KAWARTHA ARMS

FIREARM SALES & SERVICE

R.R. #4, LINDSAY, ONTARIO K9V 4R4
PHONE (705) 324-8038

Remington Arms
Ilion, N.Y. USA

Attention: FRED EMHOF

- ① What can be done regarding REM 742 ADL 308 cal
A7221998 BBL code 01 (with extra mag). The rails are
worn with very bad chatter marks, action binds when
fired. This gun is old but has seen limited use. What
type replacement costs would be involved?
- ② What can be done regarding this COOKEY 400
SN CG047914. Customer was using VIPER 1922
Lot# F11C1E. The chamber ruptured in this rifle
blowing down into the action and splitting the stock.
The customer was not hurt.

Please reply with your decisions so we can
remedy these problems.

Thank you

R. Bradburn

(Formerly ^{from} Peterborough Guns Ltd.)

NOTE - Ammo BEING SHIPPED SEPERATE - VIA UPS