

Cust. Conyd.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 BDL

GENERAL CONDITION: NEW

R # : 027443

OUTSIDE WORK: SCOPE MOUNTED

DATE: 12-22-72

FROM: KAYTON MFG. Co.

FIRE AMMO TYPE: -

ALLENTOWN, PA.

& CONDITION: _____

GUN # : 6241978

PROOF: REP-D INSP.: 74 TEST: 55

CODE: KS = 5/69

HEADING: -

GA./CAL.: 243

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR - TRIGGER CONNECTOR ENGAGEMENT O.K. TRIGGER
BINDING IN HOUSING. LUBRICATION LIKE GREASE ON
SEAR

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE LUBRICANT USED PROBABLY CAUSED
SLUGGISH TRIGGER-CONNECTOR-SEAR RETRACTION
INTO COCKED POSITION, RESULTING IN FOLLOW DOWN.