

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-00032

AL CUSTOMER ORDER NO.

IM
RECEIVED DATE OPENED DATE CODE SERIAL NUMBER NEW SERIAL NUMBER MODEL AND GRADE
1/23/92 01/04/93 OS 7-69 6262897 700 22-250 ADL
ACCESSORIES SCOPE BASE L/SIGHTS

M:

KEEGAN, KENNETH
HWC 3 BOX 24
MARTIN

Dennis
3.75 T.P. S.L. 0045
TRIG ASSY ADJUSTED OUTSIDE
OF FACTORY ADJ. SCREWS SHOW
EVIDENCE OF BEING TAMPERED WITH
UNABLE TO DUPLICATE

QUANTITY NUMBER

ACCOUNT NUMBER N/C

CONDITION

VIEW

SLIGHTLY WORN

WORN

VERY WORN

INREPAIRABLE

DAMAGED

Martin

PARTIAL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
RECEIVED	A1	B1				
TRIGGER GROUP	✓	B2			E1	F1
TRIGGER ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
D			C1	D3	E5	F5
AL			C2			

FAULT

Stk cracked along grain by butt

Unable to duplicate customer concerns

However, observation indicated that the trigger assembly adjustment screws have been tampered with outside the factory.

Trigger Pull 3.75 lb.

San Ant. 0045

COMMENTS *Stk is repairable.*

Spoke trigger assembly complete at 1/2 normal cost. as given is good will

Franklin

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
FB.		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

FD6925 REV. 1/92