

2-11-92

Remington Arms Co.

Ithaca, NY.

ATTN: Repair Div.

Dear Sirs -

I am returning The Remington  
700 BDL 308 Win. enclosed for  
inspection and repair.

IT was brought in to my shop by  
a customer who stated that while unloading  
the gun it fired while the bolt was  
being withdrawn (at about the middle of  
its length of travel) He claims his  
finger was not touching the trigger  
when it happened.

I am requesting that the gun and  
in particular the trigger be examined for  
defects and any repairs be made.  
that are necessary.

Please furnish as soon as possible  
what you believe to be the problem and  
what will be done to correct it.

I have enclosed a F.E.L. copy  
and card for your files.

Cordially, *B. J. Kersch*

Brace Kerschmer  
205 Jefferson St.  
Sch. Haven Pa 17972

Schoy/Kill