

RECEIVING AND ESTIMATING REPORT

CUST NO: 049706 C.O.D

COMMENTS

ITAL

CUSTOMER ORDER NO.

JM

006435

RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

MTN

ORDER

9/19/91

09/24/91

CH 4-87

B6859253

700 280

R 91-18831

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

KIRK, JAMES
BOX 168 RTE 70A
TABERG
USA

NY 13471

SHIP TO:

KIRK, JAMES
BOX 168 RTE 70A
TABERG
USA

NY 13471

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

10-4-91

DOOR

PAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Gun fired when safety was placed in fire position without pulling trigger

MAIN FAULT

Trigger assembly rusted from unknown source (also rust on bottom side of barrel). Internal trigger parts not moving properly. rust duplicate complaint at this time, however, rust on trigger pivot pin could have caused problem.

ARTS

Replace trigger assembly at no-charge, as gesture of good-will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 02751