

CEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-12060

CUSTOMER ORDER NO.

W/CAMO TAPE ON BBL.

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
17/93	05/19/93	RY 11-74	6801097		700 270 WIN ADL
SERIES W/STUDS					

SHIP TO:

KLEIN, RICHARD A.
221 CRESTVIEW DR
NAMPA

ID 83686

KLEIN, RICHARD A.
221 CRESTVIEW DR
NAMPAID
83686

CUST NO: 079279 C.O.D.

INT NUMBER	ACCOUNT NUMBER NC	PROM. DATE	ESTIMATED	VIA
				UPS

CONDITION	REPAIR CHARGE
W	EXCISE
HTLY WORN	TAX
JRN	INSURANCE
RY WORN	UPS
REPAIRABLE	PARCEL POST
RRD	TOTAL

OWNER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
ER GROUP	A1	B1				
ASSY.		B2			E2	F2
IL ASSY.		B3			E3	F3
SSY.		B4		D1	E4	F4
		B5		D2	E5	F5
			C1	D3		
			C2			

Wanted to duplicate customer concerns. Examination revealed
the action and bolt stop were jammed up with a sticky substance.
no need cleaning. Bolt mag. 1974

Trigger Pull 4.5 lbs
Bolt lift .006

Comments: Repaired trigger assembly. Checked at
1/2 normal replacement cost &
Clean action as per test of good will
Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
OL					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

000025 REV. 1/77