

Carl Chrysler

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 019718
OUTSIDE WORK: NO DATE: 10-5-72
FROM: K MART ENTERPR.
FIRED AMMO TYPE: - ROYAL OAK, MICH.
& CONDITION: _____ GUN #: 6258285
PROOF: R.E.P.-A ^{ASSEMBLER 90} INSP.: 58 TEST: 49 CODE: 05=7/69
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR - CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

SOLIDIFIED LUBRICANT ON SIDE OF SEAR.

COMPLAINT: "FIRES WHEN EJECTING SHELLS."

INCIDENT: FOLLOW DOWN

COMMENTS: THE SOLIDIFIED LUBRICANT CAUSED THE SEAR
TO STAY DOWN IN FIRED POSITION. WHEN THE BOLT
WAS ROTATED TO LOCK-UP, FOLLOW DOWN OCCURRED.