

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO. D916767		COMMENTS			
DATE RECEIVED 12/06/90	DATE OPENED 12/12/90	DATE CODE PD 6-83	SERIAL NUMBER B646804B	MODEL AND GRADE 700 30-06 ADL		ORDER R 90-3240	
ACCESSORIES W/STUDS							

FROM: K MART ENTERPRISES P.O. BOX 3150 TROY MI 48084		SHIP TO: K MART 4166-B0 5956 CENTRAL AVE W TOLEDO OH 43616	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE ESTIMATED VIA 1-2-91 UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *Gun fires when safety is taken off*

MAIN FAULT: *No fault found - trigger and safety assembly operates normally - Trigger pull 4#; cam - lift .072" - cannot duplicate complaint. However, trigger assembly is contaminated with staining residue (Bolt stop is sticking to receiver not moving freely). The sticky area coupled with cold temperatures could cause problems.*

PARTS: *Send quote to clean present trigger assembly (if possible) or, we can install a new trigger assembly at normal cost as a gesture of good-will if it will further restore confidence in the rifle.*

REPAIRMAN RBS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 02790