

DANA

Mr. Jeff Berman - K-Mart, General Mgr.
Central Ave.

This is my description of what is wrong
with the Remington Model "700" - Bolt
Action, 30.06 - Serial No. B6468048.

loading three (3) shells into
the chamber. With the "Safety" lever
in the safety position, and then
a shell into the barrel - the
shell discharges when the safety
lever is moved to the "Fire" position
without touching the trigger. (all
fingers outside of the trigger guard).

In other words the safety lever
becomes a trigger making the rifle
very dangerous. This occurred twice
once while raising to shoot and then
again when testing the trouble.

On the second occasion the recoil
jammed the lever back into my thumb
causing a severe laceration needing
stitches to close the wound.

Sam M. Smith

From: SAM M. SMITH

Date: 12/1/90