Remington. QUPOND

Arn Service Ret 88.23502 Hold for regely

REMINGTON ARMS COMPANY. INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357 TELEPHONE (315) 894-9961

October 20, 1988

K-Mart Store #7009-80 Attn: Mr. Jack Williams Rte. 10, Box 40 Martinsville, VA 24112

Dear Mr. Williams:

Examination has been completed on the Model 700 ADL 30-06 caliber rifle, serial number B6813018, that you returned to us because "the rifle went off while he (the customer) was holding it by the barrel in moving around in tree stand".

The returned firearm, which was produced in September of 1986, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be very good, however, it was noted that the stock contained some digs and scratches. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not produce any type of firing malfunction. All tolerances and dimensions were found to be normal. Factory seals were intact on the trigger adjustment screws, indicating no alterations were made to the trigger adjustments outside our factory. Trigger pull was measured to be 4 3/4 pounds, and sear lift with the safety in the "on-safe" position was well within specifications at .014". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.