

## RECEIVING AND ESTIMATING REPORT

R 94-16147

INITIAL	CUSTOMER ORDER NO.					
JJM	R883525					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
05/18/94	05/19/94	ON 7-93	C6810856		700 30-06 ADL	
ACCESSORIES						

FROM:

SHIP TO:

K MART ENTERPRISES  
3100 W BIG BEAVER RD  
TROY

MI 48084

K MART 9567-80  
211 N SERVICE RD E  
RUSTON

LA  
48084

CUST NO: 002510 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	FROM DATE	ESTIMATED	VIA
	059015				UPS

## GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

ALL REPAIRS OVER \$30.00 NEED TO BE QUOTED TO KMART  
PLEASE NOTE: IF YOU RECEIVE AN ESTIMATE OF WORK TO  
BE DONE AFTER THIS ACKNOWLEDGEMENT, IT MUST BE  
APPROVED BY SIGNING AND RETURNED TO US BEFORE WE CAN  
START THE WORK OUTLINED ON THE ESTIMATE.

## REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	<i>From when purchased off shelf</i>				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

## MAIN FAULT

*Mfgn 7-93 Unable to duplicate customer concern as recd. Took trigger assy  
apart, no fault found. Customer may have inadvertently pulled  
on trigger when pushing the safety lever to fire position. Exchanging  
trigger assy strictly as a gesture of good will and to restore  
customer's confidence in the rifle.*

## PARTS

*Trigger Assy Complete*

## COMMENTS

*Trigger pull measured 4 1/2 to 5 1/2  
LBS as per spec. rear sight was 10135*

*Brass Bolt ready  
Rust on barrel and receiver  
Rear Sight is Loose*

REPAIRMAN	PROOF	CLEAN <input checked="" type="checkbox"/>	TEST <input checked="" type="checkbox"/>	TARGET <input checked="" type="checkbox"/>	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 02815