

M/600 Custom Comp. Rifle

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 600

GENERAL CONDITION: NEW R #: 013900

OUTSIDE WORK: SWIVELS ADDED DATE: 7-6-72

FIRE AMMO TYPE: - FROM: AL KNABB

& CONDITION: _____ FLEETWOOD, PA.

PROOF: R.I.P. ASSEMBLER # 18 GUN #: 96981

HEADING: - INSP.: U TEST: _____ CODE: EP = 10/67

BREECH OPENING: - GR./CAL.: 6MM REM.

RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR-SEAR ENGAGEMENT, 010, MIN. 15, 020, TRIG-
GER PULL 4 POUNDS. FRONT TRIGGER ADJUSTING SCREW
BACKED OUT SO THAT TRIGGER RETRACTION IS NOT POSITIVE.
TRIGGER RUBBING LEFT SIDE OF HOUSING.

COMPLAINT: "SHELL FIRED WHEN I TOOK THE RIFLE OFF SAFETY."

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF UNDER MIN. CONNECTOR-SEAR
ENGAGEMENT, ERRATIC RETRACTION AND SLIGHT TRIGGER
BIND, RESULT IN FOLLOW DOWN.