

RECEIVING AND ESTIMATING REPORT

CUST NO: 047139 C.O.D		COMMENTS ATTN: ED JOY	
INITIAL PS	CUSTOMER ORDER NO.		
DATE RECEIVED 7/31/91	DATE OPENED 08/07/91	DATE CODE 06 7-86	SERIAL NUMBER B6803725
MODEL AND GRADE 700 270 WIN ADL		ORDER R 91-15225	
ACCESSORIES W/STUDS			

FROM:	SHIP TO:
KNAUS, KIRK L 5526 W 4TH AVE LAKEWOOD USA CO 80226	KNAUS, KIRK L 5526 W 4TH AVE LAKEWOOD USA CO 80226

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST "The problem is that the rifle on two separate occasions has fired when taking off the safety." *[Handwritten signature]*

MAIN FAULT "Cannot duplicate complaint - no fault found. Trigger and safety assembly operate properly in every respect. Trigger pull 5 1/4 pounds; action left .015" *[Handwritten signature]*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

[Handwritten note:] We can return rifle as-is or offer to replace trigger assembly at 1/2 normal charge, as a gesture of goodwill, if it will help restore confidence in the rifle.

OFFICE COPY

RD6925 REV. 7/90

PPS 02825