

Upon closer inspection of Bolt,
There appears to be a small crack
At bottom of square Lug close to
Bolt face,

Enclosed is box of shells in
separate container.

In closing I would like to add
That I have several Remington's, bot.
Rifle's and Shotguns, And I am
extremely satisfied with all of them.
I hope the sale of Remington does
not affect quality or price.

Thank you,
Steven Koleszarik

Steven Koleszarik
975 Summit Drive
Windberg, PA. 15963
814-467-5653

5
4 3/4
5

L. 009

rough indentation on
top of trigger housing, also
off to trigger housing