

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
IJM							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
11/09/91	01/15/91	LI 2-76	A6264948	700	308 ADL	R 91-01460	
ACCESSORIES		SCOPE BASE					
W/STUDS		L/REAR SIGHT					

FROM:	SHIP TO:
KUKELKORNS GUN SHOP 795 CAROLINA AVE ORANGEBURG SC 29115	KUKELKORNS GUN SHOP 795 CAROLINA AVE ORANGEBURG SC 29115

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

BASE CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *"as my customer says it has gone off three times when the safety was taken off."*

MAIN FAULT: *Trigger assembly has been improperly adjusted outside of factory - sear not missing from all adjustment screws - excessive over-travel, insufficient rear engagement - assembly not operating properly. Closing bolt foot causing firing pin to follow down.*

PARTS	<i>Send your quotation for new trigger assembly at normal cost, as gesture of good-will.</i>

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
REW					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90