


I HAVE TAKEN THE RIFLES TO LOCAL GUNSMITHS AND THEY CANNOT DO ANYTHING TO MAKE THEM WORK CONSISTANTLY IN COLD WEATHER.

AS THE TEMPERATURE DROPS THE CONDITION GOES FROM OCCASSIONAL HANG FIRE, TO MISS FIRE ON FIRST SHELL, TO COMPLETELY INOPERABLE, NOT EVEN A SLIGHT CLICK.

ADJUSTING THE TRIGGER HAS NO EFFECT.

I HAVE BEEN TOLD QUITE RECENTLY THAT THE PROBLEM IS COMMON IN 700'S AND IS DUE TO THE FIRING PIN SPRING LOOSING TENSION AS THE TEMPERATURE DROPS. IS THIS TRUE? AND IF IT IS, CAN YOU SUPPLY ME WITH NEW SPRINGS THAT ARE NOT AFFECTED BY COLD?

IF YOU DO NOT BELIEVE THIS TO BE THE PROBLEM, PLEASE ADVISE ME BY RETURN MAIL ^{WITH} INSTRUCTIONS AND ADDRESS LABELS TO RETURN THE RIFLES TO YOU FOR REPAIR, AS THEY ARE USELESS TO US IN THESE PRESENT CONDITION.

Sincerely,

MARV LANGOHR

Encl 1

MARV LANGOHR
8309 HWY 57
BAILEYS HARBOR, WI 54208