

RECEIVING AND ESTIMATING REPORT
 INITIAL: **FPS**
 DATE RECEIVED: **03/16/92**
 ACCESSORIES: **W/STUDS**

CUSTOMER ORDER NO.
 DATE OPENED: **03/26/92**
 DATE CODE: **AD 3-77**

COMMENTS: **Stekl**
WDG 2 OF 2
W/MUZZLE BRAKE
 SERIAL NUMBER: **A6426359**
 NEW SERIAL NUMBER:
 MODEL AND GRADE: **700 30-06**
BDL

ORDER: **R 92-08386**

FROM:
L'ARMURIER ALAIN BOUCHARD
420 ROUTE 143
ULVERTON QUEBEC
CANADA

SHIP TO:
L'ARMURIER ALAIN BOUCHARD
420 ROUTE 143
ULVERTON QUEBEC
CANADA

JOB 280

CUST NO: 007647 WILM

ACCOUNT NUMBER
 ACCOUNT NUMBER NC
 WRITE: ☐ **CLEAN/TEST**

PROM. DATE
 ESTIMATED: **04-1-92**
 VIA: **UPS**

GUN CONDITION
☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Unable to duplicate complaint - However trigger assembly has been inspected with outstuck factory, as evidenced by sealant missing from adjustment screws and screw not tight - firing pin sometimes follows down upon closing bolt.*
Trigger pull 4 pounds; over lift .0065"

PARTS	COMMENTS
	<i>Offer replacement trigger assembly at 1/2 through cost, as gesture of good-will.</i>
	<i>Sear engagement altered outstuck factory.</i>

REPAIRMAN RBS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE