

RECEIVING AND ESTIMATING REPORT			COMMENTS		ORDER	
INITIAL FPS	CUSTOMER ORDER NO. E45431	SPORTSMAN 78				
DATE RECEIVED 04/20/92	DATE OPENED 04/27/92	DATE CODE QJ 7-89	SERIAL NUMBER C6413520	NEW SERIAL NUMBER	MODEL AND GRADE 78 243 WIN	SPORTSMAN
ACCESSORIES W/STUDS		SCOPE BASE SOFT CASE				

FROM:	SHIP TO:
LARRYS SPORT CTR 60 OREGON CITY SHPG CTR OREGON CITY OR 97045	LARRYS SPORT CTR 60 OREGON CITY SHPG CTR OREGON CITY OR 97045

CUST NO: 007825 WILM	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C
WRITE ☐	CLEAN/TEST
PROM. DATE	ESTIMATED 3/4/92
VIA UPS	

GUN CONDITION	REPAIR CHARGE
☐ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
☐ MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.	<i>"Close bolt, firing pin fires almost all the time."</i>					
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *As received trigger assembly inoperative. Trigger assembly is contaminated with gunning substance - near safety cam - stuck to side plate of trigger housing. Improper maintenance.*

PARTS	COMMENTS
	<i>Clean present trigger assembly if possible - if not, quote new trigger assembly at \$1 normal w as a gesture of good will.</i>

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
503					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE