

Custom Compound

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 29996
OUTSIDE WORK: FRONT TRIGGER ADJUSTING DATE: 1-4-71
SCREWS RE-ADJUSTED. FROM: LEFAVOR'S SKI SHOP
FIRED AMMO TYPE: - WILMINGTON, MASS.
& CONDITION: _____ GUN #: 6369151
ASSEMBLER 13
PROOF: R.E.P.-E INSP.: 0 TEST: 98 CODE: DT-9/70
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO. APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED OR BROKEN PARTS.

COMPLAINT: "SEVERAL TIMES GUN WENT OFF WHEN CLOSING BOLT."

INCIDENT: FOLLOWS DOWN

COMMENTS: SEAR-TRIGGER CONNECTOR ENGAGEMENT .005,
MINIMUM IS .015. THIS LETS THE SEAR SLIP OFF THE
CONNECTOR UNDER PRESSURE AND FOLLON DOWN
RESULTS.