

M/700 Custom
Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 012925
OUTSIDE WORK: No DATE: 6-14-72
FROM: LEO'S CUSTOM STOCKS
FIRED AMMO TYPE: - BETHEL PARK, PENN.
& CONDITION: _____ GUN #: 6445877
PROOF: R.E.A.-N INSP.: 73 TEST: 13 CODE: PU = 6/71
HEADING: O.K. GA./CAL.: 17REM.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No - 20 ROUNDS WITH NO BLOWN PRIMERS APPROVED: _____
AFTER NEW BOLT,
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR & SEAR ENGAGEMENT .010, BOTH
CORNERS BROKEN OFF. FIRING PIN ASSEMBLY RUSTED,
BOLT BODY STAINED & FIRING PIN HOLE AT HEADING SHARP.

COMPLAINT: WHEN HE CLOSED THE BOLT ON THE FOURTH ROUND
IT WENT OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CORNER BREAKAGE ON THE SEAR AND
TRIGGER CONNECTOR, WHICH RESULTED IN FOLLOW-DOWN,
IS THE RESULT OF INSUFFICIENT ENGAGEMENT AND PRIMER
PIERCING.