

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-24393

INITIAL

CUSTOMER ORDER NO.

WOOD IS MARRED

LCS

DATE RECEIVED
11/22/91DATE OPENED
11/26/91DATE CODE
PD 6-83SERIAL NUMBER
B6464290

NEW SERIAL NUMBER

MODEL AND GRADE
700 7MM MAG

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

LEROY, KEN
716 DEPOT LANE
SULTAN
USA

WA 98294

SHIP TO:

LEROY, KEN
716 DEPOT LANE
SULTAN
USAWA
98294

CUST NO: 053714 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

- 1) Fires when bolt is closed with safety on.
2) Bolt release sticks

MAIN FAULT

Unable to duplicate complaint in factory. However, trigger assembly and bolt stop are contaminated with gunpowder residue. Trigger parts not working properly. Gear-safety cam is sticking to side plate of trigger assembly, bolt stop is sticking also. Bottom of action does examine oil concentration.
Trigger pull - 4 pounds; rear - 1 lb 0.11"

PARTS

COMMENTS

Clean front trigger assembly, if possible; if not, offer to replace with new trigger assembly at 1/2 normal cost as a gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY/TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. B

PPS 02975