

RECEIVING AND ESTIMATING REPORT ✓

COMMENTS
ATTN: JIM STEKL

CUSTOMER ORDER NO.

RECEIVED 13/91	DATE OPENED 02/21/91	DATE CODE PY 6-74	SERIAL NUMBER 6750251	MODEL AND GRADE 700 270 WIN	ORDER 91-05086
-------------------	-------------------------	----------------------	--------------------------	--------------------------------	-------------------

SERIES

L/STUDS

A:

LEWIS, D A
18130 ALTA VISTA
BUENAVISTA

CO 81211

SHIP TO:

LEWIS, D A
18130 ALTA VISTA
BUENAVISTA

CO

81211

UNIT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
-------------	--------------------	--------------------------------	------------	------------	-----------	------------

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☒ MARRED

ME'S REQUEST

"see discharged when I closed the chamber on a live round"

FAULT
As received, the trigger would not retract if the bolt stop was nearly
positive. Inspection revealed that the trigger assembly was contaminated
by a sticky residue across the bolt stop. Internal trigger parts are
moving freely. Trigger pull 5 pounds; rear lift .605". Rifle has
been properly maintained and cleaned.

Clean parent trigger assembly, if
possible; if not offer replacement
trigger assembly but at normal cost,
no gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90

PPS 02994