

Remington.



BCL. HYMC Service
R8914984
Hold for reply

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

June 14, 1989

Lewis Arms
1575 Hooksett Rd.
Hooksett, NH 03106

Gentlemen:

Examination has been completed on the Model 700 ADL 30-06 caliber rifle, serial number 6273466, that you returned to us a short time ago, because "customer states that enclosed firearm fired on closing".

The returned firearm, which was produced in September of 1969, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general condition of the gun appeared to be very good and, in going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the malfunction that was reported. All tolerances and dimensions were found to be normal. Trigger pull was measured at 5-1/2 pounds, and the sear-lift with the safety in the "on-safe" position was well within our specifications at .008". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.

Since we found the firearm to function properly in every respect, we are prepared to return it in its present condition. However, if it is desired, we will replace the trigger assembly with a new one at no-charge, as a good-will gesture, if it will restore our customer's confidence in the rifle. We will await the decision and

PPS 02997