

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL CUSTOMER ORDER NO.

JJM 5529

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

01/09/91

01/15/91

BI 1-88

C6217064

700 30-06

ADL

R

91-013

ACCESSORIES

W/STUDS

FROM:

LEWIS ARMS
1575 HOOKSETT
HOOKSETT,

NH 03106

SHIP TO:

LEWIS ARMS
1575 HOOKSETT
HOOKSETT,

NH
03106

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Problem with safety

MAIN FAULT

*Trigger assembly rusted from unknown source - internal
trigger parts not moving freely nor properly*

PARTS

*Repair trigger assembly at 700 -
charge, as gesture of good-will*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 03001