

RECEIVING AND ESTIMATING REPORT

CUST NO: 006946 TIDN		COMMENTS			
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
8/28/91	09/03/91	DU 9-71	6481228	700 7MMAG HDL	R 91-17220
ACCESSORIES			SCOPE BASE		

FROM:

LEXINGTON HDWE CO.
23 SOUTH MAIN ST.
LEXINGTON VA 24450
USA

SHIP TO:

LEXINGTON HDWE CO.
23 SOUTH MAIN ST.
LEXINGTON VA 24450
USA

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					9/12/91	UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST

"Spd rifle fired at times when doing best also at times when taking off safety. And not "touching" trigger."

IN FAULT

Cannot duplicate above complaints. However, removal of action from scope revealed that the receiver of the action is extremely dirty and dirty; also, the trigger assembly is contaminated with excessive lubrication, both wet and dried. Rifle has not been properly maintained. Trigger pull 5 pounds; clear lift .009"

- 1) Clean entire rifle
- 2) Clean trigger assembly, if possible; if not, quote new assembly at the price as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RTS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 03008