

10-3-79 RECEIVED
Down

008 L.F.T
trigger pull 1 1/4 lbs.

BUILDING 30
DENVER TECHNOLOGICAL CTR.
8301 EAST PRENTICE AVE.
ENGLEWOOD, COLO. 80110

TALL
MS INC.
E.
NN.
06602

MODEL: 700 A
R #: 25733
DATE: 10-3-79
FROM: LIBERTY MUT.
BUILDING 3
8301 E. PRENTICE
ENGLEWOOD CO
GUN #: 6853510
CODE: CZ = 4-75
GA./CAL.: 2506
CHECKED BY: M-HARDY
APPROVED: JPM 10/19/79
APPROVED: RJA 10/21/79
APPROVED: R.B. 10-18-79
APPROVED: J.S. 10-18-79
WAB 10-18-

RECOIL
CHAMBER
TEST:
COMPONENT

Old Style)

SA IN STG = 4

B. SET M U Z Z L E - barrel is added in stock
outside of plant. Barrel pad removed

COMPLAINT: GUN WHEENT OFF WHEN CHAMBERING
LIVE ROUND

INCIDENT: HOLE IN ROOF OF PICK UP TRUCK
CONCUSSION BASTE EAR DRUM

COMMENTS: Trigger assembly adjusted outside factory. Sealant
missing on 3 screws. Trigger adjusting screw has been
backed out reducing trigger pull. Trigger pull 1 1/4 #
Remington spec 3# to 5#. No return spring force on trigger.