

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-22296INITIAL
FPS

CUSTOMER ORDER NO.

ATTN: JIM STEKL
W/BTM PART OF SCOPE MNTSDATE RECEIVED
10/20/92DATE OPENED
10/23/92DATE CODE
00 7-77SERIAL NUMBER
A6478653

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

LIEPSE, ROB
133 EAST 5TH AVE
LONGMONT

CO 80501

SHIP TO:

LIEPSE, ROB
133 EAST 5TH AVE
LONGMONTCO
80501

CUST NO 068732 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☒ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

No fault found - complaint could not be duplicated after many attempts. Rifle and trigger assembly appear to operate normally, in every respect.

Trigger pull 5 1/2 pounds; over lift on

PARTS

COMMENTS

Offer the following options:
1) return rifle as-is
2) install new trigger assembly at 1/2 normal cost, do whatever is good as if that will bring back confidence in the rifle

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/9

PPS 03019