

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 07070
OUTSIDE WORK: TRIGGER ENGAGEMENT SCREW DATE: 4-23-71
SEAL REMOVED. FROM: LLOYD Co.
FIRED AMMO TYPE: - LITTLE ROCK, ARK.
& CONDITION: _____ GUN #: 6266361
ASSEMBLER 65
PROOF: R.I.P.-E INSP.: 73 TEST: 87 CODE: WS-8/69
HEADING: O.K. GA./CAL.: 22-250
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN. TRIGGER SPRING MISSING.

TRIGGER ENGAGEMENT SCREW OUT OF ADJUSTMENT.

COMPLAINT: "LEVER IN TRIGGER HOUSING BROKEN"

INCIDENT: -

COMMENTS: APPARENTLY A DEFECTIVE TRIGGER CONNECTOR WAS
USED.