

RECEIVING AND ESTIMATING REPORT

COMMENTS *to Product Service*ORDER
R 94-03871

INITIALS CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/31/94

02/01/94

DX 9-73

6625396

700 243

BDL

ACCESSORIES

W/STUDS

L/SIGHTS

FROM:

MAIDEN, GARY
HWY 522
POTNEY

KY 40865

SHIP TO:

MAIDEN, GARY
HWY 522
POTNEYKY
40865

CUST. NO: 091642 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER /VC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARREDREPAIR CHARGE *2500*

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

MAIN FAULT

PARTS

COMMENTS

*Upon receipt rifle inspection, will not load. Loading the bolt
allows the firing pin to follow down. Chamber would not the trigger only on
trigger stop seems have been triggered with correct the firing. Trigger has been
checked, and the trigger and movement below 2 lb. bolt stop above and below
with a good cleaning, bolt release will not start from being jammed up with a
steady resistance. Info. 1973*

*Before complete trigger assembly & also
check at 1/2 normal adjustment cost, as
given by. Go ahead
good work*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92