

RECEIVING AND ESTIMATING REPORT						COMMENTS		ORDER R 94-15613	
INITIAL		CUSTOMER ORDER NO.							
FDC		DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER	
		05/04/94		05/05/94		BI 1/88		A6253284	
ACCESSORIES		W/STUDS		SCOPE BASE		SWIVEL		MODEL AND GRADE	
								700 220250 REM. VARM.	
FROM:					SHIP TO:				
MAJOR TRUE VALUE JACKSON ST. HOPE					MAJOR TRUE VALUE JACKSON ST. HOPE				
IN 47240					IN 47240				
CUST NO 996940 C.O.D.									
ACCOUNT NUMBER		ACCOUNT NUMBER INC		WRITE ☐		FROM DATE		ESTIMATED	
								UPS	
GUN CONDITION								REPAIR CHARGE \$0.00	
☐ NEW								EXCISE	
☒ LIGHTLY WORN								TAX	
☐ WORN								INSURANCE	
☐ VERY WORN								UPS	
☐ UNREPAIRABLE								PARCEL POST	
☐ MARRED								TOTAL	
CUSTOMER CONCERN		AMMO		FUNCTION		FINISH		ACCURACY	
CYCLE		A1		B1					
TRIGGER GROUP				B2				E1	
BOLT ASSY.				B3				E2	
BARREL ASSY.				B4				E3	
REC. ASSY.				B5				E4	
WOOD						C1		E5	
METAL						C2		F5	
MAIN FAULT									
Upon receipt, we could not duplicate the customer concern.									
With diff. 1988 Remington model that the action and trigger assembly are found with a heavy gunning, dirty, rusted. Shot on steel and copper. Both sets were not hit.									
About									
PARTS					COMMENTS				
#26345 Trigger Assembly					Trigger just removed 5405 to 2155 and removed, same left with 5405				
					Replace complete trigger assembly and clean action at the normal replacement cost at 1/2 price of good unit.				
					Go ahead				
REPAIRMAN		PROOF		CLEAN		TEST		TARGET	
TAL									
GALLERY TESTER		DATE		DATE		DATE		DATE	
OFFICE COPY									
RD925 REV. 1/94									

to A/S
5/19/94