

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: NEW (SOME RUST) R #: 001869

OUTSIDE WORK: NO DATE: 1-28-72

FROM: MARK RD. SHTRS. SUP.

FIRE AMMO TYPE: - ERIE, PA.

& CONDITION: _____ GUN #: 6290291

PROOF: R.E.P.-F ASSEMBLER GB INSP.: 9 TEST: 55 CODE: RS-11/69

HEADING: O.K. GR./CAL.: 3006 SPG.

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS. EXTRACTOR PITTED, BOLT
BODY ALSO. SUBSTANCE RESEMBLING DRIED STEEL GROUND
ON TRIGGER & SEAR. TRIGGER PULL 2 1/2 LBS. ENGAGE-
MENT .010. LUMP ON BOLT

COMPLAINT: "FIRST SHELL HE TRIED TO CHAMBER DISCHARGED"

INCIDENT: FOLLOW DOWN

COMMENTS: THE MATERIAL ON THE SEAR & TRIGGER CAUSED
THE TRIGGER TO STICK IN FIRED POSITION. WHEN THE
ACTION WAS CLOSED THE FIRING PIN FOLLOWED DOWN
FIRING THE ROUND.