

RECEIVING AND ESTIMATING REPORT		COMMENTS	ORDER 92-10689
INITIAL JJM	CUSTOMER ORDER NO.	STAINLESS STEEL	

DATE RECEIVED 04/20/92	DATE OPENED 04/27/92	DATE CODE	SERIAL NUMBER 6711779	NEW SERIAL NUMBER	MODEL AND GRADE 700 17REM BDL
ACCESSORIES W/STUDS L/SIGHTS		OZ 7-75 2ND TIME			

FROM:	SHIP TO:
MASCHMEDT & ASSOCIATES INC 12304 32ND AVE NE SEATTLE WA 98125	MASCHMEDT & ASSOCIATES INC 12304 32ND AVE NE SEATTLE WA 98125

CUST NO: 060617 CJO.DL	ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
------------------------	----------------	--------------------	---	------------	-----------	------------

GUN CONDITION	REPAIR CHARGE
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED	EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Trigger assembly has cycled from unknown source - internal parts are not moving freely nor properly. Complaint could not be duplicated, however, it is very possible that safety condition could be the cause of the problem. Rifle has not been properly maintained.

PARTS	COMMENTS
	Replace trigger assembly at no charge, as gesture of good-will.

REPAIRMAN JTB	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE