

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/21/90	DATE OPENED 01/02/91	DATE CODE CU 4-71	SERIAL NUMBER 6419703	MODEL AND GRADE 700 22-250 ADL		ORDER R 91-000	
ACCESSORIES SCOPE BASE							

FROM:	SHIP TO:
JIM MASTERS WESTERN STORES 400 GILMER ST SULPHUR SPRINGS TX 75482	JIM MASTERS WESTERN STORES 400 GILMER ST SULPHUR SPRINGS TX 75482

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ ~~VERY~~ WORN ☒ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Discharges prematurely when foot closed after holding"

MAIN FAULT

Cannot duplicate complaint. However, trigger assembly is extremely dirty and has been improperly adjusted with the factory adjustment. As evidenced by firing action on adjustment screws. Trigger pull 6 pounds, insufficient over-travel, excessive over-travel. Rifle has not been properly maintained.

PARTS

Offer replacement trigger assembly at 1/2 normal cost, as gesture of good-will.

REPAIRMAN LFW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

stak/

RD6925 REV. 7