

RECEIVING AND ESTIMATING REPORT

COMMENTS

CROSSLIN, ROBERT

ORDER

R 91-26657

CUSTOMER ORDER NO.

RECEIVED
1/6/91

DATE OPENED
12/19/91

DATE CODE
PA 6-80

SERIAL NUMBER
B6219668

NEW SERIAL NUMBER

MODEL AND GRADE

700 7MMAG

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

M:

MAYFIELD GUN SHOP
ROUTE #4 BOX 33
MAYFIELD
USA

KY 42066

SHIP TO:

MAYFIELD GUN SHOP
ROUTE #4 BOX 33
MAYFIELD
USA

KY

42066

CUST NO:001942 ILION L

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CLE

A1

B1

GROUP GROUP

LT ASSY.

RREL ASSY.

C. ASSY.

OD

TAL

N FAULT

Trigger assembly is contaminated with gumming, sticky substance
is received, rear-safety cam was sticking to side plate of trigger
assembly - internal trigger parts not moving or working properly
cause of sticky condition.

Trigger pull - 4 1/2 pounds; Rear-lift .012"

ITS

COMMENTS

Clean present trigger assembly,
if possible; if not, offer replacement
trigger assembly at normal cost,
as a gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE