

P.I. YES GUN EXAMINATION REPORT NUMBER: 202 MODEL: 600  
 GENERAL CONDITION: FAIR R #: 33722  
 OUTSIDE WORK: RECOIL PAD ADDED STOCK DATE: 12-17-70  
CUT OUT BY REAR SIDE - Material added FROM: McBROOKS GUN  
Stock in padding COFF + F.V. 2418  
 FIRED AMMO TYPE: NOT KNOWN LUSTIN TEX.  
 & CONDITION: \_\_\_\_\_ GUN #: 6670372  
 PROOF: RFP INSP.: 93 TEST: 70 CODE: XX-12-73  
 HEADING: \_\_\_\_\_ GA./CAL.: 243  
 BREACH OPENING: \_\_\_\_\_ CHECKED BY: McHardy  
 RECOIL SHOULDERS: \_\_\_\_\_ APPROVED: 9/29/70  
 CHAMBER: \_\_\_\_\_ APPROVED: 9/29/70  
 TEST: \_\_\_\_\_ APPROVED: 9/29/70  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 1-29-E

TOO DENTED, CUT OUT BY REAR SIDE SCREWS

SCREW HOLES RECOIL PAD ADDED

1" V" on trigger assembly

COMPLAINT: SHOT HOLE THROUGH FLOOR

INCIDENT: \_\_\_\_\_

COMMENTS: Passes tick test. Sear lift .0075"  
Engagement OK, adjusting screws have not been  
tightened with.  
Unable to produce any trigger assembly malfunctions

N160