

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-27315

AL CUSTOMER ORDER NO.

JM 45560

E RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

2/06/93

12/14/93

CM 4-65

148742

700 6MM

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

DM:

F. Supus
MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

SHIP TO:

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

CUST NO: 006612 WILM

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

1-10-94

UPS

IN CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

MARRIED

Product Service

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

OLT ASSY.

B3

E2

F2

ARREL ASSY.

B4

E3

F3

EC. ASSY.

B5

E4

F4

WOOD

B6

E5

F5

METAL

B7

E6

F6

MAIN FAULT

Left off 1965. Examination revealed that the action, magazine spring and trigger assembly are covered with dirt, rust, and a safety lock. Left them then properly maintained.

COMMENTS

Replace trigger assembly and clean action at 1/2 normal replacement cost, as gesture of good will. Check over completely.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

CC

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 03292