

RECEIVING AND ESTIMATING REPORT

COMMENTS

Stekl

ORDER
R92-19540

INITIAL CUSTOMER ORDER NO.

PS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
19/16/92	09/28/92	DS 9-69	6273958		700 270 WIN BDL
ACCESSORIES	W/STUDS	SCOPE BASE	L/SIGHTS		

FROM:

SHIP TO:

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

CUST NO:006612 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
NOISE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Could not duplicate complaint after many attempts. Rifle trigger assembly operates properly in every respect. Disassembly of rifle did reveal that trigger assembly has been adjusted out of factory - original adjuster has been replaced on weight of pull of vertical adjusting screw - over travel is inadequate.

Trigger pull - 3 1/2 pounds & rear lift "002"

ARTS

COMMENTS

We can either properly adjust present trigger assembly, or install new trigger assembly at 3 point rest, even though there is nothing wrong with present assembly as a system of good-will, if that will better restore confidence in the rifle.

Offer customer above system

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

PPS 03299