

RECEIVING AND ESTIMATING REPORT						COMMENTS		ORDER R 94-02337	
INITIAL		CUSTOMER ORDER NO.							
FPS									
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE				
01/18/94	01/19/94	LD 2-77	A6413886		700 30-06		BDL		
ACCESSORIES		W/STUDS							
FROM:					SHIP TO:				
<i>F. Supply</i> MCCLELLANDS GUN SHOP DIVISION OF REMCO 1533 CENTERVILLE ROAD DALLAS TX 75228					MCCLELLANDS GUN SHOP DIVISION OF REMCO 1533 CENTERVILLE ROAD DALLAS TX 75228				
L					CUST NO: 006612 WILM L				
ACCOUNT NUMBER		ACCOUNT NUMBER NC		WRITE ☐		FROM DATE		ESTIMATED	
								VIA UPS	
GUN CONDITION						REPAIR CHARGE <i>25.00</i>			
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						EXCISE TAX INSURANCE UPS PARCEL POST TOTAL			
<i>Product Service</i>									
CUSTOMER CONCERN		AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT		
CYCLE			B1						
TRIGGER GROUP			B2			F1	F1		
BOLT ASSY.			B3			E2	F2		
BARREL ASSY.			B4		G1	F3	F3		
REC. ASSY.			B5			F4	F4		
WOOD			C1			F5	F5		
METAL			C2						
MAIN FAULT <i>Upon receipt, unable to duplicate customer concern. Examination revealed that the trigger adjustment screw had the factory contact removed. The stop screw adj. and rear engagement have been replaced. Customer report now has been resolved. See left manual page 41/2.</i>									
PARTS				COMMENTS					
				<i>Replaced complete trigger assembly with no bolt head, and then action in 1/2 second. Replacement cost, adjusted & paid.</i> <i>Go ahead</i>					
				REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
				GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD5825 REV. 1/92