

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 26, 1986

Mr. Jim McComb
4802 Precipice Cove
Austin, TX 78731

Dear Mr. McComb:

Examination has been completed on your Model 700 BDL, .270 Win. caliber, serial number B6561158, which you sent to Ilion for accidental firing reasons.

Our expert states that both trigger pull (4½ lbs) and sear lift are within industry and Remington specifications. Although we repeatedly tried to duplicate your incident, we could not do so. At this time, the rifle functions as designed.

However, we did find heavy oiling on the bottom of the receiver and in and on the trigger assembly. Trigger assemblies should not be heavily oiled as doing so may cause a malfunction, especially in cold weather.

In order to insure your complete confidence in the rifle, we are installing a new trigger assembly at no charge. After this work is performed, the firearm will be shipped, freight prepaid, to your home address.

Thank you for calling this matter to our attention, Mr. McComb, and for giving us this opportunity to be of service.

Sincerely,

A handwritten signature in dark ink, appearing to read "R.H. Potter".

R.H. Potter, Supervisor
Product Service

RHP:tpp