

RECEIVING AND ESTIMATING REPORT

COMMENTS

*to Product Service.*ORDER
R 94-07892

INITIAL CUSTOMER ORDER NO.

FJR

W/ BOTTOM HALF OF 1 SCOPE RING

DATE RECEIVED
02/25/94DATE OPENED
03/04/94DATE CODE
BC 1-82SERIAL NUMBER
B6370175

NEW SERIAL NUMBER

MODEL AND GRADE
700 243

BDL

ACCESSORIES
W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

MCQUEEN, MIKE
1609 ROLESAN LA
JONESBORO

AR 72401

SHIP TO:

MCQUEEN, MIKE
1609 ROLESAN LA
JONESBOROAR
72401

CUST NO: 093384 C-D.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER I/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ SLIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
------------------	------	----------	--------	----------	-----	---------

CYCLE	A1	B1				
-------	----	----	--	--	--	--

TRIGGER GROUP		B2				
---------------	--	----	--	--	--	--

BOLT ASSY.		B3				
------------	--	----	--	--	--	--

BARREL ASSY.		B4		D1	E3	F3
--------------	--	----	--	----	----	----

REC. ASSY.		B5		D2	E4	F4
------------	--	----	--	----	----	----

WOOD			C1	D3	E5	F5
------	--	--	----	----	----	----

METAL			C2			
-------	--	--	----	--	--	--

MAIN FAULT

*Left N/A 1982 Upon receipt, could not adjust trigger group.**Upon disassembly noted that the action, trigger assembly, and firing pin**were all bound with a sticky red substance. Trigger pin adjustment was**made and it was able to fire. No damage done.**gun is set to fire and accurate now.*

PARTS

*Trigger pin - 2 1/2 lbs**Gun bolt - .010*

COMMENTS

*Replaced trigger assembly**& clean up at 1/2 normal pressure**and in center of good hit**Go ahead*

OFFICE COPY

RD692S REV. 1/94