

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 10002
OUTSIDE WORK: TRIGGER PULL WEIGHT AND STOP DATE: 4-28-71
SCREWS RE-ADJUSTED, SCOPE MOUNTED. FROM: MAX MERMELSTEIN DIST. CO.
FIRED AMMO TYPE: _____ CARBONDALE, PENNA.
& CONDITION: _____ GUN #: 6333602
PROOF: R.I.P. - G INSP.: INCOMPLETE TEST: 55 CODE: CT = 4/70
HEADING: MAX. GA./CAL.: 25-06
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: EXCESSIVE RADIUS REAR CORNER. APPROVED: _____
CHAMBER: _____ APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED, BROKEN COMPONENTS.

COMPLAINT: "BOLT LOCKS SHUT, GUN HAS FIRED WITH SAFETY ON"
"FACTORY BULLETS SEAT IN RIFLING."

INCIDENT: _____

COMMENTS: CAN NOT DUPLICATE CUSTOMER'S "FIRED WITH SAFETY ON."
SEAR-CONNECTOR ENGAGEMENT .020 - SPECIFICATIONS MIN. .020.
THERE IS EVIDENCE OF CUSTOMER RE-ADJUSTING OF TRIGGER
STOP & PULL WEIGHT SCREWS. DECREASING TRIGGER PULL
WEIGHT REDUCES SEAR-CONNECTOR ENGAGEMENT MAKING
A FOLLOW DOWN LIKELY.