

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 BDL

GENERAL CONDITION: NEW

R # : 013324

OUTSIDE WORK: NO

DATE: 7-6-72

FROM: MEYER HOWE & SONS, INC.

FIRE AMMO TYPE: _____

GOLDEN, COLO.

& CONDITION: _____

GUN # : 6230255

PROOF: R.E.P. ASSEMBLER # 13 INSP.: 73 TEST: 87

CODE: AS = 3/69

HEADING: _____

GA./CAL.: 6 MM REM.

BRECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

CONNECTOR CLEARANCE ON TRIGGER .004 UNDER MIN. & OF
PIN TO TOP OF TRIGGER ON MAX. TRIGGER HITS TRIGGER
HOUSING. HEAVY LUBRICANT USED INSIDE HOUSING.
SAFETY P. .001 UNDER MIN. CONNECTOR CATCHES ON SEAR
WITH SAFETY ON.

COMPLAINT: "HAMMER FALLS"

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF LOW SAFETY, HIGH TRIGGER
AND TRIGGER BIND CAUSES FAILURE TO RETRACT WHEN
TRIGGER IS PULLED WITH SAFETY ON, THEN FOLLOW
DOWN WHEN SAFETY IS PUSHED OFF.