

RECEIVING AND ESTIMATING REPORT

COMMENTS

*to Product Service*ORDER
R 93-25211

INITIAL

CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/16/93

11/19/93

RC 11-82

B6148572

788 308 WIN

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

MILLERS GUN CENTER INC
JACKSON & DUPONT HWY
NEW CASTLE

DE 19720

MILLERS GUN CENTER INC
JACKSON & DUPONT HWY
NEW CASTLE

DE

19720

CUST NO 000616 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.					E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Left mfg 1982, upon receipt, unable to duplicate customer concern. Hammer would not action and trigger assembly was covered with light rust, and trigger safety mechanism. Safety assembly was more than normal. Hammer assembly. Left under good cleaning.

PARTS

COMMENTS

Replace trigger safety assembly. Then action at 1/2 normal. Cost, as per good work.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/9

PPS 03423