

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATT DENNIS SANITA

INITIAL WJS	CUSTOMER ORDER NO.					
DATE RECEIVED 12/01/89	DATE OPENED 12/06/89	DATE CODE CB 4-81	SERIAL NUMBER BB6307034	MODEL AND GRADE 700 7MM ADL		ORDER R 89-2977
ACCESSORIES W/STUDS 7MM MAUSER (7X57)						

FROM:	SHIP TO:
WM.D. MILSTER 3953 JEFFCO BLVD ARNOLD MO 63010	WM.D. MILSTER 3953 JEFFCO BLVD ARNOLD MO 63010

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	FROM DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	-----------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN-CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"As I pushed the safety forward, the rifle discharged."

MAIN FAULT

Trigger assembly, completely out of adjustment - adjusted out of factory
spring per ear engagement, no situation spring from trigger
Trigger will flip to any position when fast is released

PARTS

Replace trigger assembly at no charge
with bolt-looking style safety, per
customer's request (phone conversation
12/12/89)

Charge \$10.00 handling fee
12/12/89
JLS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD5925 REV. 6/8