

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: Good R #: 07367
OUTSIDE WORK: No DATE: 4-26-71
FROM: MONTGOMERY WARD
FIRED AMMO TYPE: -
& CONDITION: _____ GUN #: 6204725
ASSEMBLER 285
PROOF: R.F.P. INSP.: 9 TEST: 41 CODE: XR = 12/68
HEADING: O.K. GA./CAL.: 270 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No. APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED OR BROKEN COMPONENTS.

COMPLAINT: "FIRED WHEN BOLT WAS CLOSED."

INCIDENT: -

COMMENTS: COULD NOT DUPLICATE CUSTOMER'S MALFUNCTION.
HOWEVER, TRIGGER-CONNECTOR CLEARANCE BEING EXCESS-
IVE & TOO HEAVY LUBRICANT MAY HAVE CONTRIBUTED TO
SUCH A FAILURE IN COLD TEMPERATURES.
CONNECTOR .006 OVERSIZE (1.089)
TRIGGER .009 UNDERSIZE (1.067)
REPLACED TRIGGER & CONNECTOR ENGAGEMENT O.K.