

Curt. Comp.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 023622
OUTSIDE WORK: NO DATE: 11-15-72
FROM: MONTGOMERY WARD
FIRED AMMO TYPE: - RICHMOND, CAL.
& CONDITION: _____ GUN #: 6471558
PROOF: R.E.P.-L ^{ASSEMBLER 72} INSP.: 74 TEST: 53 CODE: WU= 8/71
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025
TRIGGER HOUSING PROTRUDING INTO FIRING PIN
HEAD CLEARANCE SO FIRING PIN HEAD CAN BE
PREVENTED FROM ASSUMING IT'S POSITION AGAINST
THE SEAR.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: FOLLOW DOWN

COMMENTS: THE INTERFERENCE BETWEEN FIRING PIN
HEAD AND HOUSING CREATES A BURR WHICH
CAUSES SEAR BIND. SEAR STICKS DOWN IN FIRED
POSITION RESULTING IN FOLLOW DOWN.